

**Flood Control Project Maintenance**  
**2012 Structure Summary Report**  
**Overall Unit and Item Ratings**

**Plumas County**

**North Fork Feather River Diversion Channel Drop Structure No. 1 Through 7**

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Photo Documentation	N
	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments	A
	Encroachments	A
	Culverts: Inlets / Outlets	A
	Culverts: Breaks / Holes / Cracks	A
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	N
	Electric Gate Operators	N
	Manual Gate Operators	N
	Concrete Surfaces	A
	Concrete Tilting / Settlement	A
	Concrete Foundations	A
	Security Fencing	N
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	N
	Safety	A

**Flood Control Project Maintenance**  
**2012 Structure Summary Report**  
**Overall Unit and Item Ratings**

**Plumas County (cont.)**

**North Fork Feather River Diversion Structure**

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Photo Documentation	N
	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments	A
	Encroachments	A
	Culverts: Inlets / Outlets	A
	Culverts: Breaks / Holes / Cracks	A
	Metal Pipes	A
	Trash Racks	A
	Flap Gates	N
	Sluice/Slide Gates	A
	Electric Gate Operators	N
	Manual Gate Operators	A
	Concrete Surfaces	A
	Concrete Tilting / Settlement	A
	Concrete Foundations	A
	Security Fencing	A
	Closure Structures	A
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	A
	Safety	A

**Flood Control Project Maintenance****Unit Cover Sheet****2012 Structure Inspection Results****Plumas County**

Structure
North Fork Feather River Diversion Channel Drop Structure No. 1 Through 7

Structure Rating	<b>A</b>
Date of Inspection	6/22/2012
DWR Inspector	Bob Duffey
Accompanied By	Jay Pettigrew Plumas Co.

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Structure 2012**

**Plumas County**

Structure						Structure Length	Inspection Start/End	Inspector
North Fork Feather River Diversion Channel Drop Structure No. 1 Through 7							06/22/2012 06/22/2012	Bob Duffey

  

LMR No.	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1			Structures	Photo Documentation		N		40.272710 ° 121.245750 °	40.272710 ° 121.245750 °	23 Y
2	0.00	0.00	Structures	Vegetation & Obstructions		A	Inspector Comments: All vegetation needs to be removed from the drop structure before winter.	40.272710 ° 121.245750 °	40.272710 ° 121.245750 °	1
3	0.00	0.00	Structures	Shoaling / Sedimentation		A		40.272710 ° 121.245750 °	40.272710 ° 121.245750 °	2
4	0.00	0.00	Structures	Erosion / Bank Caving		A		40.272710 ° 121.245750 °	40.272710 ° 121.245750 °	3
5	0.00	0.00	Structures	Revetments		A		40.272710 ° 121.245750 °	40.272710 ° 121.245750 °	4
6	0.00	0.00	Structures	Encroachments		A		40.272710 ° 121.245750 °	40.272710 ° 121.245750 °	5
7	0.00	0.00	Structures	Culverts: Inlets / Outlets		A		40.272710 ° 121.245750 °	40.272710 ° 121.245750 °	6
8	0.00	0.00	Structures	Culverts: Breaks / Holes / Cracks		A		40.272710 ° 121.245750 °	40.272710 ° 121.245750 °	7
9	0.00	0.00	Structures	Metal Pipes		N	Inspector Comments: This item does not apply to this inspection.	40.272710 ° 121.245750 °	40.272710 ° 121.245750 °	8
10	0.00	0.00	Structures	Trash Racks		N	Inspector Comments: This item does not apply to this inspection.	40.272710 ° 121.245750 °	40.272710 ° 121.245750 °	9
11	0.00	0.00	Structures	Flap Gates		N	Inspector Comments: This item does not apply to this inspection.	40.272710 ° 121.245750 °	40.272710 ° 121.245750 °	10
12	0.00	0.00	Structures	Sluice/Slide Gates		N	Inspector Comments: This item does not apply to this inspection.	40.272710 ° 121.245750 °	40.272710 ° 121.245750 °	11
13	0.00	0.00	Structures	Electric Gate Operators		N	Inspector Comments: This item does not apply to this inspection.	40.272710 ° 121.245750 °	40.272710 ° 121.245750 °	12
14	0.00	0.00	Structures	Manual Gate Operators		N	Inspector Comments: This item does not apply to this inspection.	40.272710 ° 121.245750 °	40.272710 ° 121.245750 °	13
15	0.00	0.00	Structures	Concrete Surfaces		A		40.296550 ° 121.259960 °	40.296550 ° 121.259960 °	14 Y
16	0.00	0.00	Structures	Concrete Tilting / Settlement		A		40.272710 ° 121.245750 °	40.272710 ° 121.245750 °	15

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Structure 2012**

**Plumas County**

Structure						Structure Length	Inspection Start/End	Inspector
North Fork Feather River Diversion Channel Drop Structure No. 1 Through 7							06/22/2012 06/22/2012	Bob Duffey

  

LMR No.	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
17	0.00	0.00	Structures	Concrete Foundations		A		40.272710 ° 121.245750 °	40.272710 ° 121.245750 °	16
18	0.00	0.00	Structures	Security Fencing		N	Inspector Comments: This item does not apply to this inspection.	40.272710 ° 121.245750 °	40.272710 ° 121.245750 °	17
19	0.00	0.00	Structures	Closure Structures		N	Inspector Comments: This item does not apply to this inspection.	40.272710 ° 121.245750 °	40.272710 ° 121.245750 °	18
20	0.00	0.00	Structures	Trash Rakes		N	Inspector Comments: This item does not apply to this inspection.	40.272710 ° 121.245750 °	40.272710 ° 121.245750 °	19
21	0.00	0.00	Structures	Other Metallic Items		N	Inspector Comments: This item does not apply to this inspection.	40.272710 ° 121.245750 °	40.272710 ° 121.245750 °	20
22	0.00	0.00	Structures	Monolith Joints		N	Inspector Comments: This item does not apply to this inspection.	40.272710 ° 121.245750 °	40.272710 ° 121.245750 °	21
23	0.00	0.00	Structures	Safety		A		40.272710 ° 121.245750 °	40.272710 ° 121.245750 °	22

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment  
C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Structure 2012**

**Plumas County**

Structure	Structure Length	Inspection Start/End	Inspector
North Fork Feather River Diversion Channel Drop Structure No. 1 Through 7		06/22/2012 06/22/2012	Bob Duffey

Levee Mile Report Line	1
Start Levee Mile	
End Levee Mile	
Location	
Category	Structures
Item	Photo Documentation

View of structure 7 looking towards 6 & 5.

rduffey\_t\_20120710\_013.jpg



Levee Mile Report Line	15
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Structures
Item	Concrete Surfaces

View of drop structure 1, looking towards the Feather River.

rduffey\_t\_20120710\_014.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance****Unit Cover Sheet**  
**2012 Structure Inspection Results****Plumas County**

Structure
North Fork Feather River Diversion Structure

Structure Rating	<b>A</b>
Date of Inspection	6/22/2012
DWR Inspector	Bob Duffey
Accompanied By	Jay Pettigrew Plumas

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Structure 2012**

**Plumas County**

Structure						Structure Length	Inspection Start/End	Inspector
North Fork Feather River Diversion Structure							06/22/2012 06/22/2012	Bob Duffey

  

LMR No.	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1			Structures	Photo Documentation		N		40.302640 ° 121.263190 °	40.302640 ° 121.263190 °	23 Y
2	0.00	0.00	Structures	Vegetation & Obstructions		A	Inspector Comments: Remove all vegetation from the face of the dam area before winter.	40.302810 ° 121.261940 °	40.302810 ° 121.261940 °	1 Y
3	0.00	0.00	Structures	Shoaling / Sedimentation		A		40.302640 ° 121.263190 °	40.302640 ° 121.263190 °	2
4	0.00	0.00	Structures	Erosion / Bank Caving		A		40.302640 ° 121.263190 °	40.302640 ° 121.263190 °	3
5	0.00	0.00	Structures	Revetments		A		40.302640 ° 121.263190 °	40.302640 ° 121.263190 °	4
6	0.00	0.00	Structures	Encroachments		A		40.302640 ° 121.263190 °	40.302640 ° 121.263190 °	5 Y
7	0.00	0.00	Structures	Culverts: Inlets / Outlets		A		40.302640 ° 121.263190 °	40.302640 ° 121.263190 °	6
8	0.00	0.00	Structures	Culverts: Breaks / Holes / Cracks		A		40.302640 ° 121.263190 °	40.302640 ° 121.263190 °	7
9	0.00	0.00	Structures	Metal Pipes		A		40.302640 ° 121.263190 °	40.302640 ° 121.263190 °	8
10	0.00	0.00	Structures	Trash Racks		A	Inspector Comments: Remove all debris from the trash rack.	40.302750 ° 121.262170 °	40.302750 ° 121.262170 °	9 Y
11	0.00	0.00	Structures	Flap Gates		N	Inspector Comments: This item does not apply to this inspection.	40.302640 ° 121.263190 °	40.302640 ° 121.263190 °	10
12	0.00	0.00	Structures	Sluice/Slide Gates		A		40.302640 ° 121.263190 °	40.302640 ° 121.263190 °	11
13	0.00	0.00	Structures	Electric Gate Operators		N	Inspector Comments: This item does not apply to this inspection.	40.302810 ° 121.261940 °	40.302810 ° 121.261940 °	12 Y
14	0.00	0.00	Structures	Manual Gate Operators		A		40.302640 ° 121.263190 °	40.302640 ° 121.263190 °	13
15	0.00	0.00	Structures	Concrete Surfaces		A		40.302640 ° 121.263190 °	40.302640 ° 121.263190 °	14
16	0.00	0.00	Structures	Concrete Tilting / Settlement		A		40.302640 ° 121.263190 °	40.302640 ° 121.263190 °	15
17	0.00	0.00	Structures	Concrete Foundations		A	Inspector Comments: There is surface cracking along the south wall of the fish ladder.	40.302640 ° 121.263190 °	40.302640 ° 121.263190 °	16

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Structure 2012**

**Plumas County**

Structure						Structure Length	Inspection Start/End	Inspector
North Fork Feather River Diversion Structure							06/22/2012 06/22/2012	Bob Duffey

  

LMR No.	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
18	0.00	0.00	Structures	Security Fencing		A		40.302640 ° 121.263190 °	40.302640 ° 121.263190 °	17
19	0.00	0.00	Structures	Closure Structures		A		40.302640 ° 121.263190 °	40.302640 ° 121.263190 °	18
20	0.00	0.00	Structures	Trash Rakes		N	Inspector Comments: This item does not apply to this inspection.	40.302640 ° 121.263190 °	40.302640 ° 121.263190 °	19
21	0.00	0.00	Structures	Other Metallic Items		N	Inspector Comments: This item does not apply to this inspection.	40.302640 ° 121.263190 °	40.302640 ° 121.263190 °	20
22	0.00	0.00	Structures	Monolith Joints		A		40.302640 ° 121.263190 °	40.302640 ° 121.263190 °	21
23	0.00	0.00	Structures	Safety		A		40.302640 ° 121.263190 °	40.302640 ° 121.263190 °	22

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment  
C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Structure 2012**

**Plumas County**

Structure	Structure Length	Inspection Start/End	Inspector
North Fork Feather River Diversion Structure		06/22/2012 06/22/2012	Bob Duffey

Levee Mile Report Line	1
Start Levee Mile	
End Levee Mile	
Location	
Category	Structures
Item	Photo Documentation

View of the dam & structure.

rduffey\_t\_20120710\_012.jpg



Levee Mile Report Line	2
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Structures
Item	Vegetation & Obstructions

View of the outfall structure & slope of the dam.

rduffey\_t\_20120710\_009.jpg



Levee Mile Report Line	6
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Structures
Item	Encroachments

Remove the debris from the upstream side of the structure.

rduffey\_t\_20120710\_015.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Structure 2012**

**Plumas County**

Structure	Structure Length	Inspection Start/End	Inspector
North Fork Feather River Diversion Structure		06/22/2012 06/22/2012	Bob Duffey

Levee Mile Report Line	10
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Structures
Item	Trash Racks
View of the trash with debris blocking the flow of water.	
rduffey_t_20120710_010.jpg	



Levee Mile Report Line	13
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Structures
Item	Electric Gate Operators
Gauging house on top of the dam, use discontinued due to vandalism.	
rduffey_t_20120710_011.jpg	

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected